

GARMIN Ltd. or its subsidiaries
c/o GARMIN International, Inc.
1200 E. 151st Street
Olathe, Kansas 66062 U.S.A.

FAA Approved AIRPLANE FLIGHT MANUAL SUPPLEMENT

GFC 600 Autopilot Installed in Textron 208B

Dwg. Number: 190-02011-07 Rev. 1

This Supplement must be attached to the FAA Approved Airplane Flight Manual when the GFC 600 Autopilot system is installed in accordance with STC SA01844WI. The information contained herein supplements the information of the basic Airplane Flight Manual. For Limitations, Procedures, and Performance information not contained in this Supplement consult the basic Pilot's Operating Handbook and FAA Approved Airplane Flight Manual.

Airplane Serial Number: _____

Airplane Registration Number: _____

FAA Approved By: _____ 

Robert G. Murray
ODA STC Unit Administrator
Garmin International, Inc
ODA-240087-CE

Date: 10/12/2018

© Copyright 2018
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this manual may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this manual and of any revision to this manual onto a hard drive or other electronic storage medium to be viewed and to print one copy of this manual or of any revision hereto, provided that such electronic or printed copy of this manual or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this manual or any revision hereto is strictly prohibited.

Garmin International, Inc.
1200 E. 151st Street
Olathe, KS 66062 USA
Telephone: 913-397-8200
www.garmin.com

Garmin International, Inc

Log of Revisions

FAA Approved Airplane Flight Manual Supplement for

**GFC 600 Autopilot
Installed in Textron 208B**

REV NO.	PAGE NO(S)	DESCRIPTION	DATE OF APPROVAL	FAA APPROVED
1	ALL	Original Issue	See Cover	See Cover

This page intentionally left blank

Table of Contents

Section 1 – General	7
USE OF THE SUPPLEMENT	7
ABBREVIATIONS AND TERMINOLOGY	8
INSTALLED EQUIPMENT INTERFACES	9
INSTALLED FEATURES CHECKLIST	10
Section 2 – Limitations	11
Section 3 – Emergency Procedures	13
AUTOPILOT MALFUNCTION / PITCH TRIM RUNAWAY.....	13
AUTOPILOT FAILURE / ABNORMAL DISCONNECT	14
ESP ACTIVATION	14
OVERSPEED PROTECTION (MAXSPEED).....	15
UNDERSPEED PROTECTION (MINSPEED).....	15
ENGINE FAILURE	16
Section 3A – Abnormal Procedures	17
AUTOPILOT PRE-FLIGHT TEST FAIL.....	17
LOSS OF AIR DATA.....	17
MANUAL AUTOPILOT DISCONNECT	17
LOSS OF NAVIGATION INFORMATION.....	18
YAW DAMPER FAILURE (if installed).....	18
ELEVATOR MISTRIM.....	19
AILERON MISTRIM	20
RUDDER MISTRIM	21
PITCH TRIM FAILURE	22
Section 4 – Normal Procedures	23
GFC 600 Power Up	23
Flight Director / Autopilot Normal Operating Procedures.....	23
VERTICAL MODES	25
LATERAL MODES.....	27
APPROACHES	31
DISABLING ESP.....	34
Section 5 – Performance	35
Section 6 – Weight and Balance	37
Section 7 – System Description	39

This page intentionally left blank

Section 1 – General

The information in this supplement is FAA-approved material and must be attached to the Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (POH/AFM) when the airplane has been modified by installation of the Garmin GFC 600 Autopilot system in accordance with Garmin International, Inc. approved data.

The information in this supplement supersedes or adds to the basic POH/AFM only as set forth below. Users of the manual are advised to always refer to the supplement for possibly superseding information and placarding applicable to operation of the airplane.

USE OF THE SUPPLEMENT

The following definitions apply to WARNINGS, CAUTIONS and NOTES found throughout the supplement:

WARNING

Operating procedures, techniques, etc., which may result in personal injury or loss of life if not carefully followed.

CAUTION

Operating procedures, techniques, etc., which may result in damage to equipment if not carefully followed.

NOTE

Operating procedures, techniques, etc., which is considered essential to emphasize.

ABBREVIATIONS AND TERMINOLOGY

The following glossary is applicable within the airplane flight manual supplement

AFCS	Automatic Flight Control System
AGL	Above Ground Level
AFM	Airplane Flight Manual
AFMS	Airplane Flight Manual Supplement
AP	Autopilot
BC	Back Course Approach
CDI	Course Deviation Indicator
CWS	Control Wheel Steering
DA	Decision Altitude
ESP	Electronic Stability and Protection
FAA	Federal Aviation Administration
FT	Feet
GA	Go Around
GFC 600	Garmin Autopilot
GI 285	Garmin Remote Autopilot Mode Annunciator Panel
GMC 605	Autopilot Mode Control Panel
GPS	Global Positioning System
HDG	AFCS heading mode
HSI	Horizontal Situation Indicator
ILS	Instrument Landing System
KIAS	Knots Indicated Airspeed
KTS	Knots
LED	Light Emitting Diode
LNAV	Lateral Navigation
LNAV + V	Lateral Navigation with Advisory Vertical Guidance
LNAV/VNAV	Lateral Navigation / Vertical Navigation Approach
LOC	Localizer (no glideslope available)
LP	Localizer Performance
LP+V	Localizer Performance with Advisory Vertical Guidance
LPV	Localizer Performance with Vertical Guidance
MDA	Minimum Descent Altitude
N/A	Not Applicable
POH	Pilot's Operating Handbook
STC	Supplemental Type Certificate
VHF	Very High Frequency
VNAV	Vertical Navigation
VOR	VHF Omni-directional Range

INSTALLED EQUIPMENT INTERFACES

The following is the list of installed equipment and functions associated with the GFC 600 Autopilot installation in this airplane.

DEVICE TYPE	Manufacturer / Model If not installed, note N/A	Additional Information
GPS Navigator #1		Roll Steering Capable? <input type="checkbox"/> YES <input type="checkbox"/> NO Is GPS #1 MapMX data provided to GFC 600 internal attitude source? <input type="checkbox"/> YES <input type="checkbox"/> NO
GPS Navigator #2		Roll Steering Capable? <input type="checkbox"/> YES <input type="checkbox"/> NO Is #2 GPS navigation interfaced to GFC 600? <input type="checkbox"/> YES <input type="checkbox"/> NO Is GPS #2 MapMX data provided to GFC 600 internal attitude source? <input type="checkbox"/> YES <input type="checkbox"/> NO
ADS-B Out Transponder with internal GPS MapMX data provided to GFC 600 internal attitude source		
Primary Flight Display		
HSI		
DG		
Air Data Computer OR; Air Data Module		Is air data provided to GFC 600 internal attitude source? <input type="checkbox"/> YES <input type="checkbox"/> NO
VHF Nav Radio #1		
VHF Nav Radio #2		Is #2 NAV interfaced to GFC 600? <input type="checkbox"/> YES <input type="checkbox"/> NO
Yaw Damper		

INSTALLED FEATURES CHECKLIST

The checked autopilot modes and features are available on this aircraft.

Basic AP Features

- ☐ Flight Director
- ☒ Control Wheel Steering
- ☐ Yaw Damper
- ☒ Manual Electric Pitch Trim
- ☒ Auto Pitch Trim
- ☒ Overspeed Protection
- ☒ Underspeed Protection

Vertical Autopilot Modes

- ☒ Pitch (PIT)
- ☒ Level (Zero vertical speed)
- ☒ Go Around (GA)
- ☒ Altitude Hold
- ☒ Vertical Speed
- ☐ Altitude Capture via Altitude Preselect
- ☒ Indicated Airspeed (IAS)
- ☐ Vertical Navigation (VNV)
- ☐ VNAV Target Alt Capture
- ☐ GPS Approach Glidepath
- ☐ ILS Glideslope

Electronic Stability and Protection

- ☒ Pitch/Roll Attitude
- ☒ High Speed Protection
- ☐ Low Speed Protection

Lateral Autopilot Modes

- ☒ Roll (ROL)
- ☒ Level (Wings Level)
- ☒ Go Around (GA)
- ☐ Heading
- ☐ GPS Navigation
 - ☐ Roll Steering
- ☐ VHF Navigation
 - ☐ VOR
- ☐ Approach Mode
 - ☐ GPS
 - ☐ VOR
 - ☐ LOC
 - ☐ LOC BC

Section 2 – Limitations

The Garmin GFC 600 Pilot's Guide, part number 190-01488-00 Rev B (or later revision), must be immediately available to the flight crew.

This AFMS is applicable to the software versions shown below:

Software Item	Software Version (or later FAA Approved version for this STC)
GFC 600 Software Version	V330200

For aircraft with an AP DISC / TRIM INT button installed only on the pilot's flight controls, a pilot must be seated in the left pilot's seat, with seatbelt fastened, during all autopilot operations.

For aircraft with an AP DISC / TRIM INT button installed on both the pilot's and copilot's flight controls, one pilot must be seated, with seatbelt fastened, during all autopilot operations.

Do not use autopilot or yaw damper during takeoff and landing.

The GFC 600 AFCS preflight test must complete successfully prior to use of the autopilot, flight director or manual electric trim.

Autopilot maximum engagement speed is 175 KIAS.

Autopilot minimum engagement speed is 80 KIAS.

The autopilot must be disengaged below 200 feet AGL during approach operations and below 800 feet AGL during all other operations.

The Autopilot must be disconnected during use of the Standby Flap System

The GFC 600 autopilot is approved for Category 1 precision approaches and non-precision approaches only.

Automatic GPS-to-LOC CDI switching must be disabled when using NAV/APR modes unless the following conditions are met:

GMC 605 software version 2.21 or later

AND

GTN 6XX/7XX software version 6.50 or later

AND

G500/600 with software version 7.30 or later OR G500/600 TXi with software version 2.20 or later.

NOTE

The GFC 600 installation does not change the previously approved kinds of operation. Refer to the aircraft AFM.

This page intentionally blank

Section 3 – Emergency Procedures

Some emergency situations require immediate memorized corrective action. These steps are printed in bold in the emergency procedures and should be accomplished without the aid of the checklist.

AUTOPILOT MALFUNCTION / PITCH TRIM RUNAWAY

If the airplane deviates unexpectedly from the planned flight path:

1. **Control Wheel** **GRIP FIRMLY**
2. **AP DISC / TRIM INT Button** **PRESS AND HOLD**
3. **Aircraft Attitude** **MAINTAIN / REGAIN AIRCRAFT CONTROL**

NOTE

Do not release the AP DISC / TRIM INT Button until after pulling the AUTOPILOT circuit breaker. Pulling the AUTOPILOT circuit breaker will render the autopilot and yaw damper (if installed) inoperative.

4. Elevator Trim RE-TRIM if necessary using Pitch Trim Wheel
5. AUTOPILOT Circuit Breaker PULL
6. AP DISC / TRIM INT Button RELEASE

WARNING

IN FLIGHT, DO NOT OVERPOWER THE AUTOPILOT. THE TRIM WILL OPERATE IN THE DIRECTION OPPOSING THE OVERPOWER FORCE, WHICH WILL RESULT IN LARGE OUT-OF-TRIM FORCES.

DO NOT ATTEMPT TO RE-ENGAGE THE AUTOPILOT OR USE MANUAL ELECTRIC PITCH TRIM UNTIL THE CAUSE OF THE MALFUNCTION HAS BEEN CORRECTED.

AUTOPILOT FAILURE / ABNORMAL DISCONNECT

(Red LED, AP FAIL in Message Window on GMC 605 display, Continuous aural tone)

1. AP DISC / TRIM INT ButtonPRESS AND RELEASE
(to cancel disconnect tone)
2. Aircraft Attitude MAINTAIN / REGAIN AIRCRAFT CONTROL

NOTE

The autopilot disconnect may be accompanied by an AP FAIL on the GMC 605 Status message window, indicating the automatic flight control system has failed. The autopilot cannot be re-engaged with this annunciation present.

ESP ACTIVATION

1. Power..... AS REQUIRED
2. Aircraft Attitude MAINTAIN / REGAIN AIRCRAFT CONTROL
3. LVL key PRESS to engage autopilot

NOTE

If ESP is active for at least 50% of the last 20 seconds, the autopilot will automatically engage in LVL mode, an aural 'ENGAGING AUTOPILOT' will be played, and the autopilot will roll the wings level and fly at zero-vertical speed. Refer to Section 7 – System Description for further information.

4. SELECT desired autopilot modes

OVERSPEED PROTECTION (MAXSPEED)

(MAXSPEED in Message Window on GMC 605 display)

1. **Power**..... **REDUCE**

2. **Aircraft Attitude and Altitude** **MONITOR**

After overspeed condition is corrected:

3. Autopilot RESELECT VERTICAL AND LATERAL MODES (if necessary)

4. Power ADJUST AS NECESSARY

NOTE

Overspeed protection mode provides a pitch up command to decelerate the airplane at or below the maximum autopilot operating speed. Overspeed protection will not activate in altitude hold (ALT), glideslope (GS), or glidepath (GP) modes.

UNDERSPEED PROTECTION (MINSPEED)

(AIRSPEED Aural sounds, MINSPEED in Message Window on GMC 605 display)

1. **Power**..... **INCREASE POWER AS REQUIRED TO CORRECT UNDERSPEED**

2. **Aircraft Attitude and Altitude** **MONITOR**

After underspeed condition is corrected:

3. Autopilot RESELECT VERTICAL AND LATERAL MODES (if necessary)

4. Power ADJUST AS NECESSARY

NOTE

Autopilot Underspeed Protection Mode provides a pitch down command to maintain 2 KIAS above stall warning airspeed if the selected vertical mode is ALT, GS, GP, or GA. Otherwise, Underspeed Protection will maintain 85 KIAS.

If the autopilot was in ALT, GS, GP, or GA modes when Underspeed Protection was entered, the autopilot will roll wings level.

This page intentionally blank

Section 3A – Abnormal Procedures

AUTOPILOT PRE-FLIGHT TEST FAIL

(Red LED illuminated next to AP key, AP FAIL in Message Window on GMC 605 display)

Indicates the AFCS system failed the automatic Pre-Flight test. The autopilot, yaw damper (if installed), ESP, and electric elevator trim are inoperative. Flight Director may still function.

LOSS OF AIR DATA

(AIRDAT FAIL in Message Window on GMC 605 display)

If pressure altitude, indicated airspeed, or true airspeed is invalid or missing, AIRDAT FAIL is displayed in the message window. This indicates that any mode dependent on air data may not be supported such as ESP high speed, ESP low speed, OSP, USP, IAS, VS, or ALT modes.

MANUAL AUTOPILOT DISCONNECT

If necessary, the autopilot may be manually disconnected using any one of the following methods.

1. AP DISC / TRIM INT Button PRESS and RELEASE
(Control wheel)
2. AP Button (GMC 605 mode control panel) PRESS
(Yaw damper remains engaged)
3. Pitch Trim Switch..... ACTIVATE either half of the split switch
(Yaw damper remains engaged)
4. AUTOPILOT Circuit Breaker PULL

LOSS OF NAVIGATION INFORMATION

(Amber FD LED flashes for 10 seconds, GPS, VOR, LOC, VAPP, or BC flashes for 10 seconds on GMC 605 mode panel display)

NOTE

If a navigation signal is lost while the autopilot is tracking it, the autopilot will roll the aircraft wings level and default to roll mode (ROL).

1. GMC 605 Mode Panel..... SELECT HDG mode and SET desired heading
2. NAV Source.....SELECT a valid nav source
3. GMC 605 Mode Panel.....SELECT NAV

If on an instrument approach at the time the navigation signal is lost:

4. Missed Approach ProcedureEXECUTE (as applicable)

YAW DAMPER FAILURE (if installed)

(Amber YD LED, YD FAIL in Message Window on GMC 605 display)

1. Indicates a failure of the yaw damper. The yaw damper will disconnect. The autopilot may be re-engaged and disengaged normally, but the yaw damper will remain inoperative.
2. Autopilot AS DESIRED

ELEVATOR MISTRIM

(Amber AP LED flashes for 10 seconds, ELE TRM UP or ELE TRM DN displayed in Message Window on GMC 605 display)

Indicates a mistrim of the elevator while the autopilot is engaged. The autopilot will normally trim the airplane as required. However, during rapid acceleration, deceleration, configuration changes, or near either end of the elevator trim limits, momentary illumination of this message may occur. If the autopilot is disconnected while this message is displayed, high elevator control forces are possible.

WARNING

Do not attempt to overpower the autopilot in the event of a pitch mistrim. The autopilot servo will oppose pilot input and will cause pitch trim to run opposite the direction of pilot input. This will lead to a significant out-of-trim condition, resulting in large control wheel force when disengaging the autopilot.

NOTE

Momentary display of the ELE TRIM UP or ELE TRIM DN message during configuration changes or large airspeed changes is normal.

1. Control Wheel.....GRIP FIRMLY

WARNING

Be prepared for significant sustained control forces in the direction of the mistrim annunciation. For example, ELE TRM DN indicates nose down control wheel force will be required upon autopilot disconnect.

2. AP DISC / TRIM INT SwitchPRESS AND RELEASE
3. Manual Elevator TrimRE-TRIM as required
4. The autopilot should be considered inoperative until the cause of the mistrim has been investigated and corrected. Yaw damper may be re-engaged and used normally.

AILERON MISTRIM

(Amber AP LED flashes for 10 seconds, AIL TRM LF or AIL TRM RT displayed in Message Window on GMC 605 display)

Indicates a mistrim of the ailerons while the autopilot is engaged. If the autopilot is disconnected while this message is displayed, high aileron control forces are possible.

NOTE

Observe the 200 pound maximum fuel imbalance limitation.

1. RUDDER TRIM.....VERIFY slip / skid indicator is centered
2. AILERON TRIM.....ROTATE SLOWLY in the direction of indicated mistrim until message clears

If annunciation remains:

3. CONTROL WHEEL.....GRIP FIRMLY

WARNING

Be prepared for significant sustained control forces in the direction of the mistrim annunciation. For example, AIL TRM RT indicates right wing down control wheel force will be required upon autopilot disconnect.

4. AP DISC / TRIM INT switchPRESS
5. AUTOPILOT.....If lateral trim is re-established, RE-ENGAGE

RUDDER MISTRIM

(Amber AP LED flashes for 10 seconds, RUD TRM LF or RUD TRM RT displayed in Message Window on GMC 605 display)

Indicates a mistrim of the rudder while the yaw damper is engaged. If the yaw damper is disconnected while this message is displayed, high rudder pedal forces and yawing motion are possible.

1. RUDDER TRIM.....ADJUST as required to extinguish

If annunciation remains:

2. RUDDER PEDALS and CONTROL WHEEL.....HOLD FIRMLY

WARNING

Be prepared for significant sustained control forces in the direction of the mistrim annunciation. For example, RUD TRM RT indicates right rudder pedal force will be required upon yaw damper disconnect.

3. AP DISC / TRIM INT switchPRESS
4. AUTOPILOT.....If rudder trim is re-established, RE-ENGAGE

PITCH TRIM FAILURE

(Amber AP LED, PTRM FAIL in Message Window on GMC 605 display)

Indicates a failure of the pitch trim servo of the autopilot. The autopilot may remain engaged, but after disengagement it cannot be re-engaged until the problem is resolved. The yaw damper (if installed) will remain operative.

1. Control Wheel GRIP FIRMLY
2. AP DISC / TRIM INT Button PRESS and RELEASE
(Be prepared for possible high elevator control forces)
3. Elevator Trim RE-TRIM if necessary using Pitch Trim Wheel

NOTE

The autopilot disconnect may be accompanied by an AP FAIL on the GMC 605 Status message window, indicating the automatic flight control system has failed. The autopilot cannot be re-engaged with this annunciation present.

4. Yaw Damper ENGAGE AS REQUIRED

Section 4 – Normal Procedures

GFC 600 Power Up

During power-up of the GFC 600 system, an initialization splash screen displays on the GMC 605 Mode Selection Panel. The splash screen displays the following information:

- GFC 600 title
- Electronic Stability and Protection (ESP)
- Software version number

When this information has been reviewed, the pilot is prompted to continue (CONT) by pressing the HDG key and the GFC 600 enters preflight test.

During the preflight test the GMC 605 will display PFT in the Message Window. LED fault lights on the GMC 605 autopilot mode panel cycle through a test sequence, three amber lights followed by three red lights, then extinguish if the preflight test successfully passes. The autopilot disconnect tone sounds at the completion of the preflight test. If the GFC 600 passes preflight test, the display on the GMC 605 will be blank and all LED fault lights extinguished.

If the GI 285 remote autopilot mode display is installed, it will cycle through an annunciator light test during the GFC 600 preflight test. All lateral mode annunciations will illuminate amber, followed by AP, YD, TRIM annunciations in amber, all vertical mode annunciations illuminated amber, and finally the AP, YD, and TRIM annunciations in red. If the preflight test passes, all annunciations on the GI 285 will extinguish.

Flight Director / Autopilot Normal Operating Procedures

Autopilot/Flight Director mode annunciations on the GMC 605 displayed in bold fonts indicate active autopilot/flight director modes. Armed modes are indicated in smaller fonts. Normal mode transitions will flash inverse video for 10 seconds before becoming steady. Abnormal mode transitions will flash for 10 seconds before the default mode is annunciated as the active mode. Default autopilot/flight director modes are Roll (ROL) and Pitch (PIT) modes.

If installed, active modes are indicated on the GI 285 Annunciator Panel in green, and armed modes in white. Abnormal mode transitions will flash amber for 10 seconds before the default mode is annunciated as the active mode in green.

The GMC 605 display panel is divided into three sections. From left to right the sections are, lateral autopilot modes, vertical autopilot modes, and the message window.



GMC 605 Autopilot Mode Control Panel



GI 285 Annunciator Panel

Autopilot Engagement — The autopilot may be engaged by pushing the AP Key on the GMC 605 Mode Control Panel. A green LED will illuminate indicating the autopilot is engaged in the active modes as shown on the display.

Autopilot Engagement with Flight Director Off — Upon engagement, the autopilot will be set to hold the current attitude of the airplane, if the flight director was not previously on. In this case, 'ROL' and 'PIT' will be annunciated.

Autopilot Engagement with Flight Director On — If the flight director is on, the autopilot will smoothly pitch and roll the airplane to capture the FD command bars. The prior flight director modes remain unchanged.

Autopilot Disengagement — The most common way to disconnect the autopilot is to press and release the AP DISC / TRIM INT Switch located on the control stick. An autopilot disconnect tone will sound and annunciated on the GMC 605/GI 285. Other ways to disconnect the autopilot include:

- Pressing the AP Key on the GMC 605 Mode Controller
- Operating either side of the Electric Pitch Trim Switch (located on the control wheel)
- Pulling the AUTOPILOT circuit breaker

In the event of unexpected autopilot behavior, press and hold the AP DISC / TRIM INT switch to disconnect the autopilot and remove all power to the servos.

VERTICAL MODES

VERTICAL SPEED (VS) MODE

1. Press VS Button, autopilot synchronizes to the airplane's current vertical speed.
2. Vertical Speed Reference ADJUST using NOSE UP/DN Wheel

INDICATED AIRSPEED (IAS) MODE

1. Press IAS Button, autopilot synchronizes to the airplane's current indicated airspeed.
2. AIRSPEED Reference ADJUST using NOSE UP / DN Wheel
3. POWER.....ADJUST as required

ALTITUDE HOLD (ALT) MODE

1. When at the desired altitude, PRESS the ALT Key. The autopilot will hold the altitude at which the ALT key was pressed.

NOTE

If climbing or descending at a high rate when the ALT button is pressed, the airplane will overshoot the reference altitude and then return to it. The amount of overshoot will depend on the vertical speed when the ALT button is pressed.

2. If altitude preselect is available with a compatible PFD:
To capture a selected altitude:
 - a) Altimeter Setting ADJUST to appropriate value
 - b) Altitude Preselect.....SET to desired altitude
 - c) Vertical Mode and Reference.....SELECT on GMC 605

GO AROUND (GA)

1. Control Wheel GRASP FIRMLY
2. GO AROUND button PRESS – Verify GA / GA on GMC 605
autopilot will not disengage
3. Autopilot VERIFY airplane pitches up following flight director command bars
4. Power.....APPLY Go Around power
5. Flaps.....If flaps are set to 30°, SET 20°
6. After reaching a safe altitude and airspeed, retract flaps. A minimum of 400 ft AGL and 100 KIAS is recommended.
7. GMC 605 Mode Panel PRESS **NAV** to couple to selected navigation source
OR;
PRESS **HDG** to Fly ATC Assigned Missed Approach Heading
8. Altitude Preselect (if installed) VERIFY Set to appropriate altitude

NOTE

The pilot is responsible for initial missed approach guidance in accordance with published procedure. When the GA button is pressed the Flight Director command bars will command go-around pitch attitude and wings level. The pilot must select the CDI to the appropriate navigation source and select the desired lateral and vertical flight director modes.

VERTICAL NAVIGATION (VNV)

(Optional Feature)

1. Navigation Source SELECT CDI to GPS
2. Vertical Navigation Profile LOAD into the GPS navigator flight plan
3. Altitude Preselect.....ADJUST to desired altitude below current altitude
4. GMC 605 VNV Key.....PRESS
5. Bold or subdued font VPTH annunciation..... VERIFY on GMC 605

NOTE

If the altitude preselect is not set at least 75ft below the current aircraft altitude, the autopilot will not capture the vertical navigation path.

The autopilot will capture the vertical navigation path from above or below.

TRANSITION to ILS APPROACH from VERTICAL NAVIGATION

(Optional Feature)

1. Navigation Source SELECT CDI to GPS
2. Approach Procedure LOAD into the GPS navigator's flight plan
3. CDI SET / VERIFY desired track
4. Altitude Preselect ADJUST to desired altitude below current altitude
5. GMC 605 VNV Key PRESS
6. Bold or subdued font VPTH annunciation VERIFY on GMC 605
7. GMC 605 APR Key PRESS
8. Bold or subdued font LOC and GS annunciations VERIFY on GMC 605
9. Airspeed MAINTAIN 90 KIAS or greater (recommended)

NOTE

If the altitude preselect is not set at least 75ft below the current aircraft altitude, the autopilot will not capture the vertical navigation path.

The autopilot can capture the vertical navigation path from above or below.

Under certain display conditions, VPTH and GS armed modes are combined into a single "GS/V" annunciation.

If the Course Deviation Indicator (CDI) is greater than half-scale deflection, the autopilot will arm the LOC mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the APR key is pressed.

When the selected navigation source is an ILS, glideslope coupling is automatically armed when the APR key is pressed. The glideslope cannot be captured until the localizer is captured. The autopilot can capture the glideslope from above or below the glideslope.

TRANSITION to GPS APPROACH from VERTICAL NAVIGATION

(Optional Feature)

1. Navigation Source SELECT CDI to GPS
2. Approach Procedure LOAD into the GPS navigator's flight plan
3. CDI SET / VERIFY desired track
4. Altitude Preselect ADJUST to desired altitude below current altitude
5. GMC 605 VNV Key PRESS
6. Bold or subdued font VPTH annunciation VERIFY on GMC 605
7. GMC 605 APR Key PRESS
8. Bold or subdued font GPS and GP annunciations VERIFY on GMC 605
9. Airspeed MAINTAIN 90 KIAS or greater (recommended)

NOTE

If the altitude preselect is not set at least 75ft below the current aircraft altitude, the autopilot will not capture the vertical navigation path.

The autopilot can capture the vertical navigation path from above or below.

Under certain display conditions, VPTH and GP armed modes are combined into a single "GP/V" annunciation.

If the Course Deviation Indicator (CDI) is greater than half-scale deflection, the autopilot will arm the GPS mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the APR key is pressed.

When the selected GPS approach includes vertical guidance (LPV, LNAV/VNAV, LNAV+V, LP+V), glidepath coupling is automatically armed when the APR key is pressed. The glidepath cannot be captured until the lateral approach path is captured. The autopilot can capture the glidepath from above or below the glidepath.

LATERAL MODES

HEADING MODE (HDG)

1. HDG Key PRESS
2. HDG Knob ROTATE to set heading bug to desired heading

NOTE

If heading bug is rotated quickly, the airplane could turn in the opposite direction as the heading bug's movement.

3. When the airplane reaches the heading bug, the autopilot will roll the wings level to track the heading reference.

NAVIGATION (VOR)

1. Navigation Source.SELECT CDI to VHF NAV
Tune and identify the station frequency
2. CDI SET / VERIFY course

If HSI is installed:

3. Intercept HeadingESTABLISH in HDG or ROL mode (if required)

If DG is installed (no HSI):

3. Desired VOR radial.....ALIGN aircraft on desired VOR radial
- 3a. HDG Bug (on DG)SET course
4. GMC 605 NAV keyPRESS
5. Bold or subdued font VOR annunciationVERIFY on GMC 605

NOTE

If the Course Deviation Indicator (CDI) is greater than half scale deflection, the autopilot will arm the VOR mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the NAV key is pressed.

In aircraft with a DG installed and no HSI, VOR mode cannot be armed. HDG mode must be used to align the aircraft on the selected course with less than half scale deflection prior to pressing the NAV key.

NAVIGATION (GPS)

1. Navigation Source SELECT CDI to GPS
2. Flight Plan LOAD in GPS navigator
3. CDI SET / VERIFY desired track

If HSI is installed:

4. Intercept Heading ESTABLISH in HDG or ROL mode (if required)

If DG is installed:

4. Active Navigation LegALIGN aircraft on active navigation leg using HDG mode
- 4a. HDG Bug (on DG)SET desired track
5. GMC 605 NAV key PRESS
6. Bold or subdued font GPS annunciationVERIFY on GMC 605

NOTE

If the Course Deviation Indicator (CDI) is greater half scale deflection, the autopilot will arm the GPS mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the NAV key is pressed.

In aircraft with a DG installed and no HSI, GPS mode cannot be armed. HDG mode must be used to align the aircraft on the active course with less than half scale deflection prior to pressing the NAV key.

APPROACHES

ILS

1. Navigation Source.SELECT CDI to VHF Nav
Tune and Identify an ILS station frequency
 2. CDISET / VERIFY course
- If HSI is installed:
3. Intercept HeadingESTABLISH in HDG or ROL mode (if required)
- If DG is installed (no HSI installed):
3. Final Approach Course ALIGN aircraft on final approach course using HDG mode
 - 3a. HDG Bug (on DG) SET course
4. GMC 605 APR KeyPRESS
 5. Bold or subdued font LOC and GS annunciationsVERIFY on GMC 605
 6. AirspeedMAINTAIN 90 KIAS or greater (recommended)

NOTE

If the Course Deviation Indicator (CDI) is greater than half scale deflection, the autopilot will arm the LOC mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the APR key is pressed.

When the selected navigation source is an ILS, glideslope coupling is automatically armed when the APR key is pressed. The glideslope cannot be captured until the localizer is captured. The autopilot can capture the glideslope from above or below the glideslope.

In aircraft with a DG installed and no HSI, LOC mode cannot be armed. HDG mode must be used to align the aircraft on the approach course with less than half scale deflection prior to pressing the APR key.

GPS

1. Navigation SourceSELECT CDI to GPS
2. Approach Procedure SELECT in GPS Navigator
3. CDISET / VERIFY desired track
- If HSI is installed:
 4. Intercept HeadingESTABLISH in HDG or ROL mode (if required)
- If DG is installed (no HSI):
 4. Approach CourseALIGN aircraft on approach course using HDG mode
 - 4a. HDG Bug (on DG) SET desired track
5. GMC 605 APR KeyPRESS
6. Bold or subdued font GPS and GP annunciationsVERIFY on GMC 605
7. Vertical Mode and Reference..... SELECT on GMC 605
If required for GPS approach without vertical guidance
8. AirspeedMAINTAIN 90 KIAS or greater (recommended)

NOTE

If the Course Deviation Indicator (CDI) is greater than half scale deflection, the autopilot will arm the GPS mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the APR key is pressed.

When the selected GPS approach includes vertical guidance (LPV, LNAV/VNAV, LNAV+V, LP+V), glidepath coupling is automatically armed when the APR key is pressed. The glidepath cannot be captured until the lateral approach path is captured. The autopilot can capture the glidepath from above or below the glidepath.

In aircraft with a DG installed and no HSI, GPS mode cannot be armed. HDG mode must be used to align the aircraft on the approach course with less than half scale deflection prior to pressing the APR key.

VOR

1. Navigation Source.SELECT CDI to VHF Nav
Tune and Identify a VOR station frequency
2. CDISET / VERIFY course
- If HSI is installed:
 3. Intercept HeadingESTABLISH in HDG or ROL mode (if required)
- If DG is installed (no HSI installed):
 3. Final Approach CourseALIGN aircraft on final approach course using HDG mode
 - 3a. HDG Bug (on DG)SET course
4. GMC 605 APR KeyPRESS
5. Bold or subdued font VAPP annunciationVERIFY on GMC 605
6. AirspeedMAINTAIN 90 KIAS or greater (recommended)
7. Vertical Mode and Reference..... SELECT on GMC 605

NOTE

If the Course Deviation Indicator (CDI) is greater than half scale deflection, the autopilot will arm the VAPP mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the APR key is pressed.

In aircraft with a DG installed and no HSI, VAPP mode cannot be armed. HDG mode must be used to align the aircraft on the approach course with less than half scale deflection prior to pressing the APR key.

BC

1. Navigation SourceSELECT CDI to VHF Nav
Tune and Identify a LOC BC station frequency
 2. CDISET / VERIFY localizer front course
- If HSI is installed:
3. Intercept HeadingESTABLISH in HDG or ROL mode (if required)
- If DG is installed (no HSI installed):
3. Final Approach CourseALIGN aircraft on final approach course using HDG mode
 - 3a. HDG Bug (on DG) SET localizer front course
4. GMC 605 BC KeyPRESS
 5. Bold or subdued font BC annunciationVERIFY on GMC 605
 6. Vertical Mode and Reference..... SELECT on GMC 605
 7. AirspeedMAINTAIN 90 KIAS or greater (recommended)

NOTE

If the Course Deviation Indicator (CDI) is greater than half scale deflection, the autopilot will arm the BC mode. The pilot must ensure that the current heading will result in a capture of the selected course. If the CDI is within half scale deflection, the autopilot will enter the capture mode when the BC key is pressed.

In aircraft with a DG installed and no HSI, BC mode cannot be armed. HDG mode must be used to align the aircraft on the approach course with less than half scale deflection prior to pressing the BC key.

DISABLING ESP

(ESP OFF message displayed in Message Window on GMC 605 display)

ESP can be disabled with the following procedure. ESP will be re-enabled when either the AP or FD keys are pressed. The GMC 605 Mode Control Panel will display the message "ESP OFF" when ESP is disabled.

1. AP DISC / TRIM INT switch.....PRESS and HOLD 5 seconds

Section 5 – Performance

No Change.

This page intentionally blank

Section 6 – Weight and Balance

The addition of the GFC 600 autopilot has been accounted for in the aircraft's basic empty weight and center of gravity. The aircraft loading and CG envelope remain unchanged after the installation of the GFC 600 system. Refer to the AFM limitations section.

This page intentionally blank

Section 7 – System Description

AFCS OVERVIEW

The GFC 600 is a digital Automatic Flight Control System (AFCS). It is a two-axis autopilot (with optional 3rd axis yaw damper) and flight director system which provides the pilot with the following features:

Flight Director (FD) — The flight director processing occurs in the GMC 605 mode panel. Selected modes for the flight director are displayed on the GMC 605 display and the GI 285 annunciator panel (if installed).

The flight director provides:

- Command Bars showing pitch/roll guidance
- Vertical / lateral mode selection and processing

Autopilot (AP) — Autopilot operation occurs within the pitch, roll, and pitch trim servos. It also provides servo monitoring, and automatic flight control in response to flight director steering commands, attitude and rate information, and airspeed.

Optional Yaw Damper (YD) — The yaw servo is self-monitoring and provides Dutch roll damping and turn coordination in response to yaw rate, roll angle, lateral acceleration, and airspeed.

Electric Pitch Trim — The pitch trim servo provides manual electric pitch trim capability when the autopilot is not engaged. It provides automatic electric pitch trim capability when the autopilot is engaged.

Internal Attitude Source — The GMC 605 contains internal sensors which calculate the aircraft attitude, allowing the GFC 600 to operate without relying on any external source of attitude. Internal monitoring detects attitude errors and will automatically disconnect the autopilot in the unlikely event of internal attitude failure. The GMC 605 attitude source requires either air data or GPS data for calculation of the aircraft attitude.

Airspeed and Altitude Information — The GFC 600 requires airspeed and altitude information. It may be interfaced to an external air data computer. If an external air data computer is not available, a small Air Data Module will be attached to the back of the GMC 605 rack to provide basic air data information to the GFC 600.

Pilot commands to the AFCS are entered through the GMC 605 autopilot mode panel.

Other components of the AFCS include the GSA 87 pitch, roll, optional yaw, and pitch trim servos that also contain autopilot processors, control wheel mounted elevator trim switch, control wheel mounted autopilot / yaw damper disconnect and trim interrupt switch (AP DISC / TRIM INT), Control Wheel Steering switch (CWS), and a Go-Around (GA) switch.

The following conditions will cause the autopilot to automatically disconnect:

- Electrical power failure, including pulling the AUTOPILOT circuit breaker.
- Internal autopilot system failure (including internal attitude source failure)

The internal attitude source will fail with the loss of both air data and GPS to the GMC 605 internal attitude source. (In some installations, only air data or only GPS may be interfaced to the GMC 605 internal attitude source). See installed equipment interface checklist on page 9 of this AFMS for information for installed interfaces.

The following pilot actions will cause the autopilot to disconnect:

- Pressing the red AP DISC / TRIM INT switch on the pilot's (and optionally copilot's) control wheel
- Actuating either half of the manual electric trim split switch
- Pushing the AP key on the GMC 605 mode controller when the autopilot is engaged
- Pulling the AUTOPILOT circuit breaker

The red AP DISC / TRIM INT switch on the pilot's control wheel (and optionally copilot's) will interrupt power to the manual electric trim for as long as the switch is depressed.

AFCS CONTROL UNIT



The following tables list the available AFCS vertical and lateral modes with their corresponding controls and annunciations. The NOSE UP/DN Wheel can be used to change the vertical mode reference while operating in Pitch Hold, Vertical Speed, Altitude Hold, or Flight Level Change mode. Increments of change and maximum ranges of values for each of these references using the NOSE UP/DN Wheel are also listed in the table.

AFCS VERTICAL MODES

Vertical Mode	Control	Annunciation	Reference Range	Reference Change Increment
Pitch Hold	(default)	PIT	20° Nose up 15° Nose Down	0.5°
Selected Altitude Capture	*	ALTS		
Altitude Hold	ALT Key	ALT nnnnn FT		10 ft
Vertical Speed	VS Key	VS nnnn FPM	-2000 to +1500 fpm	100 fpm
IAS Hold	IAS Key	IAS nnn KTS	80 to 175 kt	1 kt
Vertical Path Tracking (VNAV)	VNV Key	VPTH		
Glidepath	APR Key	GP		
Glideslope		GS		
Go Around	GA Switch	GA	7°	
Level (LVL)	LVL Key	LVL	Zero Vertical Speed	
ESP High Pitch Engagement			ESP High Pitch Attitude engages at 16.5° nose up	
ESP Low Pitch Engagement			ESP Low Pitch Attitude engages at 16.5° nose down	
ESP High Airspeed Engagement			ESP High Airspeed engages at 176 KIAS	
ESP Low Airspeed Engagement			When above 200 ft AGL, ESP Low Airspeed engages when stall warning activates. (This mode only available if height above terrain is available from a compatible Garmin GPS).	

* ALTS arms automatically when PIT, VS, IAS, or GA is active, if the aircraft is equipped with altitude preselect.

AFCS LATERAL MODES

Lateral Mode	Control	Annunciation	Maximum Roll Command Limit
Roll Mode	(default)	ROL	25°
Heading Select	HDG Key	HDG	25°
Navigation, GPS Arm/Capture/Track	NAV Key	GPS	30°
Navigation, VOR Enroute Arm/Capture/Track		VOR	25°
Navigation, LOC Arm/Capture/Track (No Glideslope)		LOC	25°
Backcourse Arm/Capture/Track	BC Key	BC	25°
Approach, GPS Arm/Capture/Track (Glidepath Mode Automatically Armed, if available)	APR Key	GPS	30°
Approach, VOR Arm/Capture/Track		VAPP	25°
Approach, ILS Arm/Capture/Track (Glideslope Mode Automatically Armed)		LOC	25°
Go Around	GA Switch	GA	Wings Level
LVL (Level)	LVL Key	LVL	Wings Level
ESP Roll Attitude Engagement	ESP Roll Attitude engages at 45°		

The CWS Button does not change lateral references for Heading Select, Navigation, Backcourse, or Approach modes. The autopilot guides the aircraft back to the Selected Heading/Course upon release of the CWS Button.

The autopilot may be engaged within the following ranges:

Pitch 50° nose up to 50° nose down
Roll ±75°

If the above pitch or roll limits are exceeded while the autopilot is engaged, the autopilot will disconnect. Engaging the autopilot outside of its command limits, but within its engagement limits, will cause the autopilot to return the aircraft within command limits. The autopilot is capable of commanding the aircraft in the following ranges:

Pitch 20° nose up to 15° nose down
Roll ±30°

PREFLIGHT TEST

During the preflight test the GMC 605 will display PFT in the Message Window. LED fault lights on the GMC 605 autopilot mode panel cycle through a test sequence, three amber lights for one second, followed by three red lights for one second, then extinguish if the preflight test successfully passes. The autopilot disconnect tone sounds at the completion of the preflight test. If the GFC 600 passes preflight test, the display on the GMC 605 will be blank and all LED fault lights extinguished. If GFC 600 fails the PFT, PFT FAIL is displayed in the message window the AP LED in red illuminates.

If the GI 285 remote autopilot mode display is installed, it will cycle through an annunciator light test during the GFC 600 preflight test. All lateral mode annunciations will illuminate amber, followed by AP, YD, TRIM annunciations in amber, all vertical mode annunciations illuminated amber, and finally the AP, YD, and TRIM annunciations in red. If the preflight test passes, all annunciations on the GI 285 will extinguish.

MESSAGES

GMC 605 Messages	
AIL TRM LF	Aileron Trim Left - Autopilot is holding left wing down roll force. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.
AIL TRM RT	Aileron Trim Right - Autopilot is holding right wing down roll force. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.
AIRDAT FAIL	Air data input to the GFC 600 has failed. Vertical modes that require air data input are failed.
ALT KEY STK	ALT key stuck – System has sensed ALT key input for 30 seconds or longer.
AP FAIL	Autopilot Failed – The autopilot is inoperative. Red AP LED will flash until the pilot presses the AP key. Once AP FAIL acknowledged, the Red AP LED will be steady. If installed, the GI 285 AP indicator illuminates red.
AP KEY STK	Autopilot key stuck – System has sensed AP key input for 30 seconds or longer.
APR KEY STK	Approach key stuck – System has sensed APR key input for 30 seconds or longer.
BC KEY STK	Back Course key stuck – System has sensed BC key input for 30 seconds or longer.
CWS	System is in Control Wheel Steering mode. If installed, the GI 285 AP indicator illuminates white.
DISABLD KEY	Disabled Key – The pressed key is inactive; it has no associated mode. This message will extinguish after 3 seconds.

GMC 605 Messages	
ELE TRM DN	Elevator Trim Down – Autopilot is holding elevator nose down force. The pitch trim needs to be adjusted nose down. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.
ELE TRM UP	Elevator Trim Up – Autopilot is holding elevator nose up force. The pitch trim needs to be adjusted nose up. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.
ESP FAIL	Electronic Stability and Protection Has Failed – ESP function is not available.
ESP OFF	Electronic Stability and Protection is OFF – The pilot has turned ESP OFF.
FD KEY STK	Flight Director key stuck – System has sensed FD key input for 30 seconds or longer.
HDG KEY STK	Heading key stuck – System has sensed HDG key input for 30 seconds or longer.
IAS KEY STK	Indicated Airspeed key stuck – System has sensed IAS key input for 30 seconds or longer.
LVL KEY STK	Level Mode key stuck – System has sensed LVL key input for 30 seconds or longer.
MAXSPEED	Autopilot Overspeed Protection mode is active.
MINSPEED	Autopilot Underspeed Protection mode is active.
NAV KEY STK	Nav Mode key stuck – System has sensed NAV key input for 30 seconds or longer.
P TRIM FAIL	Pitch Trim Fail – Autopilot and Manual Electric Pitch Trim is inoperative. Amber AP LED flashes for 10 seconds and becomes steady. If installed, the GI 285 TRIM indicator illuminates in yellow.
PFT FAIL	Preflight Test Failed – Autopilot failed the preflight test. The autopilot is inoperative. FD modes may still be available. Red AP LED illuminates steady. If installed, the GI 285 AP indicator illuminates red.
PFT	Preflight Test is in Progress.
RUD TRM LF	Rudder Trim Left – Yaw Damper is holding left rudder force. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.

GMC 605 Messages	
RUD TRM RT	Rudder Trim Right – Yaw Damper is holding right rudder force. Amber AP LED flashes amber for 5 seconds then remains steady amber. If installed, the GI 285 TRIM indicator illuminates yellow.
SET HDG=CRS	When the GFC 600 is configured to use a DG (not an HSI), the heading bug must be set to the desired track or navigation course when in NAV or APPROACH modes. This message will be displayed continuously when NAV or APPROACH modes are active.
VNV KEY STK	Vertical Navigation Mode key stuck – System has sensed VNV key input for 30 seconds or longer.
VS KEY STK	Vertical Speed Mode key stuck – System has sensed VS key input for 30 seconds or longer.
YD FAIL	Yaw Damper has failed. Amber YD LED flashes for 10 seconds and becomes steady. If installed, the GI 285 YD indicator illuminates yellow.
YD KEY STK	Yaw Damper key stuck – System has sensed YD key input for 30 seconds or longer. Yaw damper is inoperative.

LED ANNUNCIATOR LIGHTS

GMC 605 / GI 285 GREEN LED LIGHTS	
AP	Steady Green AP LED - Autopilot is engaged and functioning.
FD	Steady Green FD LED - Flight Director is displayed and functioning. (There is no FD indication on the GI 285)
YD	Steady Green YD LED - Yaw Damper is operating
GMC 605 / GI 285 AMBER LED LIGHTS	
AP	Flashing Amber AP LED for 5 seconds, then extinguish – Normal AP disconnect OR; Flashing Amber AP LED displayed on the GMC, and flashing yellow TRIM displayed on the GI 285, for 10 seconds then steady, accompanied by a GMC 605 message for ELE, AIL, or RUD mistrim message – See abnormal procedure for mistrim message.

GMC 605 / GI 285 AMBER LED LIGHTS (continued)	
FD	Flashing Amber FD LED for 10 seconds, then extinguish – The coupled lateral or vertical mode has been lost, and the GMC has reverted to ROL mode (if lateral mode was lost) or PIT mode (if vertical mode was lost).
YD	<p>Amber flashing YD LED for 10 seconds, then extinguished - Normal YD disconnect</p> <p>Flashing Amber YD LED for 10 seconds, then steady – Abnormal YD disconnect</p> <p>Flashing Amber YD LED for 10 seconds, then steady, accompanied by a GMC 605 message for ELE or AIL mistrim message – See abnormal procedure for mistrim message.</p> <p>Steady Amber YD LED – Failed Yaw Damper – YD FAIL in message window</p>
TRIM (GI 285)	<p>Flashing yellow TRIM displayed on the GI 285, for 10 seconds, then steady, accompanied by a GMC 605 message for ELE, AIL, or RUD mistrim message – See abnormal procedure for mistrim message.</p> <p>OR;</p> <p>Steady yellow TRIM displayed on the GI 285, accompanied by a GMC 605 P TRIM FAIL message. – Autopilot and Manual Electric Trim is inoperative.</p>
Lateral or Vertical Mode (GI 285)	Abnormal mode transitions will flash yellow for 10 seconds before the default mode is annunciated as the active mode in green.
GMC 605 / GI 285 RED LED LIGHTS	
AP	<p>Continuous Flashing Red AP LED – Abnormal AP disconnect</p> <p>Steady Red AP LED – Autopilot Fail. Cause of the failure will be annunciated in the message window.</p>
FD	Not used
NO ILLUMINATED LED LIGHT	
AP	Autopilot is OFF
FD	Flight Director is OFF
YD	Yaw Damper is OFF

LIGHTING

GMC 605 mode panel and GI 285 annunciator panel lighting (if installed) may be controlled by an aircraft dimming bus if the system is configured for dimming bus operation. If not controlled by dimming bus, lighting is controlled by integrated photocells which sense the ambient cockpit lighting.